

**GOVERNMENT OF TELANGANA  
ROADS & BUILDINGS DEPARTMENT**

From :  
Sri Y.Srinivasa Mutrhy, B.E.,  
Executive Engineer(R&B),  
Medchal Division.  
Medchal – Malkajgiri District

✓ To :  
The Principal  
St.Anthony School  
H.No:5-70,5-71,5-74  
Gundlapochampally  
Medchal-Malkajgiri District

Lr. No.EE / (R&B)/DB/Medchal/2022-23 / 91      Date: 10.06.2022

Sir,

Sub :- (R&B) Division, Medchal-Malkajgiri Dist - Issue of Structural Soundness Certificate for St. Anthony School, H.No. 5-70, 5-71, 5-74 Gundlapochampally, Medchal-Malkajgiri District – Reg.


Ref:- 1) Requisition Lr. from Principal, St. Anthony School, Gundlapochampally Dt. 26-05-2022

2) DEE/Buildings Lr. no. DEE/(R&B)/Buildings/2022-23/40, Dt. 02-06-2022

Adverting to the ref 1<sup>st</sup> cited The Principal, St. Anthony School situated at H.No 5-70, 5-71, 5-74 Gundlapochampally, Medchal-Malkajgiri District with GPS Co-ordinates of Latitude 17.5737625, Longitude 78.4788281 has applied for issuance of Structural Soundness Certificate.

Further based on the report of the DEE/R&B, Buildings sub-Division and based on the structural soundness certificate issued by Sri B. Tirupati, M.Tech Structural Engineer with License No. 409, Structural Engineer-GHMC/TP-10, structure is good and sound and structural soundness certificate is herewith issued for the period of One (1) year only for **Academic Year 2022-2023 for a period of one Year only**

Yours faithfully,

  
Executive Engineer (R&B)  
( Dist (R&B) Officer)  
Medchal-Malkajgiri Dist

*B.16*

Copy to the DyEE/R&B, Buildings sub-Division for information and necessary action.